



Product Change Notification

TE Connectivity

Product Change Notification: P-19-016789

PCN Date: 15-JAN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Tubing products impacted by new Prop 65

Description of Changes

This PCN is to inform our customers of additional labelling on some Tubing products. The requirements of the Proposition 65 (Prop 65) a Californian Safe water and Toxic Enforcement Act of 1986 now requires that we warn customers that some of our tubing products contain Antimony in the material make up. This requirement only applies to customer in California. However, as TE cannot predict which products will arrive with customers in California we have to label all Antimony containing products, of course these products will be delivered also to customers outside of California. No Action needs to be taken by our customers outside of California unless the products you receive are directly being forwarded through the supply chain to further customer in California USA in which case the warning must accompany the product. Please share this information with your colleagues so they will also be informed.

Reason for Changes:

Product improvement.To comply with Californian Prop 65 regulations.

Estimated Dates:

Last Order Date (Obsolete Parts Only): **First Date To Ship** (Changed Parts Only):

16-JAN-2019

Last Ship Date (Obsolete Parts Only): **Last Date for Mixed Shipments:** (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
030791-000	NO			"7-1190238-4", "VERSAFIT-3/4-0-FSP"			
042787J001	NO			"2-1190328-1", "V4-1.5-0-SP-SM"			
063725P017	NO			"5-1190481-7", "ES2000-NO.2-B9-0-40MM"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
074713-000	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
137963J001	NO			"6-1191000-7", "V2-1.5-0-SP-SM"			
1637114002	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
182083-000	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
235265J001	NO			"6-1191730-1", "V2-27.0-0-FSP-SM"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
269647-000	NO			"1-1191990-6", "ES-CAP-HW-NO.3-M8-0-45MM"			
2748174003	NO			"5-1192035-7", "VERSAFIT-3/32-6-SP"			
3647544004	NO			"4-1192735-1", "VERSAFIT-1-1/4-0-SP"			
4177514031	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
4411054001	NO			"9-1193316-4", "DCPT-9/3-45-SP"			
457079J001	NO			"2-1193430-1", "V4-3.5-0-SP-SM"			
467625-000	NO			"1193505-8", "RNF-100-1-YO-FSP"			
4951522003	NO			"6-1193702-6", "ATUM-32/8-0-STK"			
5020054016	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
5020114003	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			
5038924001	NO			"1193795-8", "DCPT-8/4-45-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5053024047	NO			"8-1193836-7", "RNF-100-1/8-BU-SP", "RNF-100-1/8-6"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053244040	NO			"3-1193869-5", "RNF-100-3/4-0-SP"			
5053294053	NO			"4-1193876-8", "RNF-100-1-0-SP"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
5053492029	NO			"1-1193889-0", "RNF-100-4-BK-STK"			
5067454043	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
5068174005	NO			"2-1193938-0", "CGPT-3.2/1.6-4-SP"			
5068184005	NO			"3-1193938-7", "CGPT-4.8/2.4-4-SP"			
5068204006	NO			"7-1193938-8", "CGPT-9.5/4.8-4-SP"			
5069804009	NO			"8-1193947-2", "CGPT-1.6/0.8-0-SP"			
5069824023	NO			"8-1193948-3", "CGPT-3.2/1.6-0-SP"			
5069854021	NO			"8-1193951-7", "CGPT-9.5/4.8-0-SP"			
5069884015	NO			"8-1193954-3", "CGPT-25.4/12.7-0-SP"			
5110554007	NO			"9-1194016-4", "ATUM-8/2-0-SP"			
5129894001	NO			"6-1194030-3", "CGPT-9/3-0-SP"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
532301J001	NO			"7-1194179-0", "V2-9.0-0-FSP-SM"			
543633P051	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500752003	NO			"2-1194337-2", "TAT-125-2-0-STK"			
5500762006	NO			"4-1194337-1", "TAT-125-3-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5509114058	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
5634732003	NO			"3-1194451-8", "ATUM-12/3-0-STK"			
5677624001	NO			"1194499-9", "RNF-3000-1.5/0.5-2-SP"			
6106994002	NO			"4-1194829-3", "ATUM-24/8-2-SP"			
6464574002	NO			"1-1195105-0", "NETM1000-8-0-SP"			
687401J001	NO			"2-1195398-4", "V2-28.0-0-FSP-SM"			
7024702003	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
7501716003	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
755533-000	NO			"8-1195888-8", "VERSAFIT-1/2-6-FSP"			
895231P008	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
9531154004	NO			"4-1197380-2", "CGAT-9/3-0-SP"			
C53800-000	NO			"7-1200721-2", "VERSAFIT-3/16-KT2-REFILL"			
C72402-000	NO			"7-1200726-2", "VERSAFIT-KIT-6-0"			
C87605-000	NO			"8-1200721-3", "VERSAFIT-1/4-KT2-REFILL"			
CB5045-000	NO			"8-1899832-6"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			
CB5337-000	NO						
CF3962-000	NO						
CH26084001	NO			"ATUM-3/1-9-SP", "6-1899587-0"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
EG40970001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB07066001	NO			"BATTU-12.7/6.1-A1-0-32MM"			
NB07106001	NO			"8-1899840-2", "BATTU-20.1/8.9-A1-0-39MM"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			
NB09542001	NO			"ATUM--16/4-0-STK"			
NB09654001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
030791-000	NO			"7-1190238-4", "VERSAFIT-3/4-0-FSP"			
042787J001	NO			"2-1190328-1", "V4-1.5-0-SP-SM"			
063725P017	NO			"5-1190481-7", "ES2000-NO.2-B9-0-40MM"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
137963J001	NO			"6-1191000-7", "V2-1.5-0-SP-SM"			
1637114002	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
182083-000	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
2748174003	NO			"5-1192035-7", "VERSAFIT-3/32-6-SP"			
3647544004	NO			"4-1192735-1", "VERSAFIT-1-1/4-0-SP"			
4177514031	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
4951522003	NO			"6-1193702-6", "ATUM-32/8-0-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5053024047	NO			"8-1193836-7", "RNF-100-1/8-BU-SP", "RNF-100-1/8-6"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
5053492029	NO			"1-1193889-0", "RNF-100-4-BK-STK"			
532301J001	NO			"7-1194179-0", "V2-9.0-0-FSP-SM"			
543633P051	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5634732003	NO			"3-1194451-8", "ATUM-12/3-0-STK"			
6464574002	NO			"1-1195105-0", "NETM1000-8-0-SP"			
7024702003	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
C53800-000	NO			"7-1200721-2", "VERSAFIT-3/16-KT2-REFILL"			
C72402-000	NO			"7-1200726-2", "VERSAFIT-KIT-6-0"			
C87605-000	NO			"8-1200721-3", "VERSAFIT-1/4-KT2-REFILL"			
EG40970001	NO						
NB09542001	NO			"ATUM--16/4-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
030791-000	NO			"7-1190238-4", "VERSAFIT-3/4-0-FSP"			
042787J001	NO			"2-1190328-1", "V4-1.5-0-SP-SM"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
074713-000	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
137963J001	NO			"6-1191000-7", "V2-1.5-0-SP-SM"			
1637114002	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
182083-000	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
235265J001	NO			"6-1191730-1", "V2-27.0-0-FSP-SM"			
2748174003	NO			"5-1192035-7", "VERSAFIT-3/32-6-SP"			
3647544004	NO			"4-1192735-1", "VERSAFIT-1-1/4-0-SP"			
4177514031	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
4411054001	NO			"9-1193316-4", "DCPT-9/3-45-SP"			
457079J001	NO			"2-1193430-1", "V4-3.5-0-SP-SM"			
467625-000	NO			"1193505-8", "RNF-100-1-YO-FSP"			
4951522003	NO			"6-1193702-6", "ATUM-32/8-0-STK"			
5020054016	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
5020114003	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			
5038924001	NO			"1193795-8", "DCPT-8/4-45-SP"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5053024047	NO			"8-1193836-7", "RNF-100-1/8-BU-SP", "RNF-100-1/8-6"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053492029	NO			"1-1193889-0", "RNF-100-4-BK-STK"			
5067454043	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
5110554007	NO			"9-1194016-4", "ATUM-8/2-0-SP"			
532301J001	NO			"7-1194179-0", "V2-9.0-0-FSP-SM"			
543633P051	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5509114058	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
5634732003	NO			"3-1194451-8", "ATUM-12/3-0-STK"			
5677624001	NO			"1194499-9", "RNF-3000-1.5/0.5-2-SP"			
6106994002	NO			"4-1194829-3", "ATUM-24/8-2-SP"			
6464574002	NO			"1-1195105-0", "NETM1000-8-0-SP"			
7024702003	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
755533-000	NO			"8-1195888-8", "VERSAFIT-1/2-6-FSP"			
C53800-000	NO			"7-1200721-2", "VERSAFIT-3/16-KT2-REFILL"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
C72402-000	NO			"7-1200726-2", "VERSAFIT-KIT-6-0"			
C87605-000	NO			"8-1200721-3", "VERSAFIT-1/4-KT2-REFILL"			
CB5045-000	NO			"8-1899832-6"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			
NB09542001	NO			"ATUM--16/4-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
030791-000	NO			"7-1190238-4", "VERSAFIT-3/4-0-FSP"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
074713-000	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
1637114002	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
182083-000	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
235265J001	NO			"6-1191730-1", "V2-27.0-0-FSP-SM"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
269647-000	NO			"1-1191990-6", "ES-CAP-HW-NO.3-M8-0-45MM"			
4177514031	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
4411054001	NO			"9-1193316-4", "DCPT-9/3-45-SP"			
457079J001	NO			"2-1193430-1", "V4-3.5-0-SP-SM"			
467625-000	NO			"1193505-8", "RNF-100-1-YO-FSP"			
5020054016	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
5020114003	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			
5038924001	NO			"1193795-8", "DCPT-8/4-45-SP"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5053244040	NO			"3-1193869-5", "RNF-100-3/4-0-SP"			
5053294053	NO			"4-1193876-8", "RNF-100-1-0-SP"			
5067454043	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
5068174005	NO			"2-1193938-0", "CGPT-3.2/1.6-4-SP"			
5068184005	NO			"3-1193938-7", "CGPT-4.8/2.4-4-SP"			
5068204006	NO			"7-1193938-8", "CGPT-9.5/4.8-4-SP"			
5069804009	NO			"8-1193947-2", "CGPT-1.6/0.8-0-SP"			
5069824023	NO			"8-1193948-3", "CGPT-3.2/1.6-0-SP"			
5069854021	NO			"8-1193951-7", "CGPT-9.5/4.8-0-SP"			
5069884015	NO			"8-1193954-3", "CGPT-25.4/12.7-0-SP"			
5110554007	NO			"9-1194016-4", "ATUM-8/2-0-SP"			
5129894001	NO			"6-1194030-3", "CGPT-9/3-0-SP"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
5500752003	NO			"2-1194337-2", "TAT-125-2-0-STK"			
5500762006	NO			"4-1194337-1", "TAT-125-3-0-STK"			
5509114058	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
5677624001	NO			"1194499-9", "RNF-3000-1.5/0.5-2-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6106994002	NO			"4-1194829-3", "ATUM-24/8-2-SP"			
6464574002	NO			"1-1195105-0", "NETM1000-8-0-SP"			
687401J001	NO			"2-1195398-4", "V2-28.0-0-FSP-SM"			
7501716003	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
755533-000	NO			"8-1195888-8", "VERSAFIT-1/2-6-FSP"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
9531154004	NO			"4-1197380-2", "CGAT-9/3-0-SP"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			
CB5337-000	NO						
CF3962-000	NO						
CH26084001	NO			"ATUM-3/1-9-SP", "6-1899587-0"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
030791-000	NO			"7-1190238-4", "VERSAFIT-3/4-0-FSP"			
074713-000	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
1637114002	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
4177514031	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
4411054001	NO			"9-1193316-4", "DCPT-9/3-45-SP"			
457079J001	NO			"2-1193430-1", "V4-3.5-0-SP-SM"			
467625-000	NO			"1193505-8", "RNF-100-1-YO-FSP"			
5020054016	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
5020114003	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			
5038924001	NO			"1193795-8", "DCPT-8/4-45-SP"			
5067454043	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
5110554007	NO			"9-1194016-4", "ATUM-8/2-0-SP"			
5509114058	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
5677624001	NO			"1194499-9", "RNF-3000-1.5/0.5-2-SP"			
6464574002	NO			"1-1195105-0", "NETM1000-8-0-SP"			
755533-000	NO			"8-1195888-8", "VERSAFIT-1/2-6-FSP"			
CB5045-000	NO			"8-1899832-6"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
030791-000	NO			"7-1190238-4", "VERSAFIT-3/4-0-FSP"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
074713-000	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
1637114002	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
182083-000	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
235265J001	NO			"6-1191730-1", "V2-27.0-0-FSP-SM"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
269647-000	NO			"1-1191990-6", "ES-CAP-HW-NO.3-M8-0-45MM"			
4177514031	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
4411054001	NO			"9-1193316-4", "DCPT-9/3-45-SP"			
457079J001	NO			"2-1193430-1", "V4-3.5-0-SP-SM"			
467625-000	NO			"1193505-8", "RNF-100-1-YO-FSP"			
5020054016	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
5020114003	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			
5038924001	NO			"1193795-8", "DCPT-8/4-45-SP"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5053244040	NO			"3-1193869-5", "RNF-100-3/4-0-SP"			
5053294053	NO			"4-1193876-8", "RNF-100-1-0-SP"			
5067454043	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
5068174005	NO			"2-1193938-0", "CGPT-3.2/1.6-4-SP"			
5068184005	NO			"3-1193938-7", "CGPT-4.8/2.4-4-SP"			
5068204006	NO			"7-1193938-8", "CGPT-9.5/4.8-4-SP"			
5069804009	NO			"8-1193947-2", "CGPT-1.6/0.8-0-SP"			
5069824023	NO			"8-1193948-3", "CGPT-3.2/1.6-0-SP"			
5069854021	NO			"8-1193951-7", "CGPT-9.5/4.8-0-SP"			
5069884015	NO			"8-1193954-3", "CGPT-25.4/12.7-0-SP"			
5110554007	NO			"9-1194016-4", "ATUM-8/2-0-SP"			
5129894001	NO			"6-1194030-3", "CGPT-9/3-0-SP"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
5500752003	NO			"2-1194337-2", "TAT-125-2-0-STK"			
5500762006	NO			"4-1194337-1", "TAT-125-3-0-STK"			
5509114058	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
5677624001	NO			"1194499-9", "RNF-3000-1.5/0.5-2-SP"			
6106994002	NO			"4-1194829-3", "ATUM-24/8-2-SP"			
6464574002	NO			"1-1195105-0", "NETM1000-8-0-SP"			
687401J001	NO			"2-1195398-4", "V2-28.0-0-FSP-SM"			
7501716003	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
755533-000	NO			"8-1195888-8", "VERSAFIT-1/2-6-FSP"			
895231P008	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
9531154004	NO			"4-1197380-2", "CGAT-9/3-0-SP"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			
CB5337-000	NO						
CF3962-000	NO						
CH26084001	NO			"ATUM-3/1-9-SP", "6-1899587-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
NB07066001	NO			"BATTU-12.7/6.1-A1-0-32MM"			
NB07106001	NO			"8-1899840-2", "BATTU-20.1/8.9-A1-0-39MM"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			
NB09654001	NO						