



## Product Change Notice (PCN)

**Date: 2/6/2019**

**PCN Number: PCN-0451070R-01**

To Our Customers:

We appreciate your use of CUI products. Our commitment in maintaining and improving processes is demonstrated by plans to enhance our product quality, reliability and manufacturability. The purpose of this notice is to inform you of a product change.

Product(s) Affected: PJ-028-SMT-TR, PJ-071, PJ-029-SMT-TR

Reason(s) for Change: The existing mold of PJ-028-SMT-TR, PJ-071 and PJ-029-SMT-TR (shared plastic mold) is unable to maintain an efficient production level. In order to maintain quality and lead-time of production, a new mold has been developed. We have taken this opportunity to optimize the product design and to enhance the quality of the overall process. The new mold will enhance the appearance and the electrical structure while maintaining fit, form, and function of the final product.

Description of Change: Photos of changes included below

Affected Date Code: 4/30/2019

Product Availability: Currently available

Additional Information: No change to form, fit, or function

PCN Approval:

Operations/Quality







A handwritten signature in black ink that reads "Sam Woody".

---


Product Marketing

A handwritten signature in black ink that reads "Ryan Dekmar".

# Comparison plastic housing as below:


	New version	Current version
Front	 <p>No change</p>	 <p>No change</p>
Back	 <p>add chamfer</p> <p>clear mark</p> <p>with mark</p>	 <p>no chamfer</p> <p>unclear mark</p> <p>no mark</p>
Left	 <p>with mark</p>	 <p>no mark</p>

Right



with mark


injection point




no mark

injection point

Top




with mark



no mark

Bottom



with mark

outlook different

mark position



no mark

outlook different

mark position