

Global Change Notification (GCN)

Product Family	Multimode 12-24-48 Product fiber Family Products	10685369
		GCN Number
Series	Multiple	June 29, 2015
		Date Issued
Reason For Change	Manufacturing Process Change	
Change Description	This letter is to inform you that as part of our Continuous Improvement program, we are modifying the speed, time, pressure and lapping film sequence in the polishing process in order to reduce the scratches and pits of the product and then increasing the first pass yield. This change will not affect the performance of the products.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Not Applicable	
Assessment Of Change (How Product Will Be Qualified & Validated)	There is no Change in Fit, Form or Function	
Internal Molex Qualification Date (Planned Date Information Available)	April 22, 2015	
Sample Availability Date (Changed Part)	April 22, 2015	
Date of Implementation	December 30, 2015	
Method of Identifying Change	Parts produced after the implementation date	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com